



Inspection Report

Customer	BCA Sweden	Cosmetic Grade	3
Registration Number	GDA69F	Mechanical Grade	A

Vehicle Data

Nissan Leaf Leaf Acenta 40 kWh - 2019

Vehicle Identification Number	SJNFAAZE1U0067887	Odometer Reading	95436 km
First Registration / Construction Year	2019-07-01 / 2019-06-01	Inspection Date / Place	2025-04-30 / Kareby
Fuel Type	Battery Electric Vehicle	Gearbox Type	Automatic
Colour	White	Number of Keys	2
Service Book Available	Present	Service History	94354 60997 21802
Last Service Km / Date	94354 / 2025-02-05	Arrival Date	2025-04-29

Mounted Tires

Tyre / Wheel Type	Summer
	//R16 / 4 mm
	//R16 / 3 mm
	//R16 / 5 mm
	//R16 / 5 mm

Unmounted Tires

Tyre / Wheel Type	Four Seasons
	//R16 / 5 mm
	//R16 / 8 mm
	//R16 / 4 mm
	//R16 / 8 mm

Equipment

• Heated steering wheel	• Bluetooth
• Cruise control	• Digital Radio
• Reversing Camera	• Satellite navigation

Comments Test Drive

Comment

Checklist

Testdriven

Damage

	Component	Damage
1	Tailgate Upholstery / Back	Interior / Scratched
2	Door Step / Front Right	Interior / Scratched
3	Dashboard / Front	Interior / Stained
4	EV charging port	Bodywork / Breakage
5	Shield / Front	Bodywork / Dent / Dent
6	Rocker Panel / Center Right	Bodywork / Dent / Deformation
7	Door / Back Right	Bodywork / Dent / Deformation
8	Fender / Back Right	Bodywork / Dent / Deformation
9	Shield / Back	Paint / Scratch / Scuff
10	Fender / Back Left	Bodywork / Dent / Dent
11	Door / Back Left	Bodywork / Dent / Dent


Photo Documentation













1. Tailgate Upholstery / Back
Interior / Scratched



2. Door Step / Front Right
Interior / Scratched




3. Dashboard / Front

Interior / Stained



4. EV charging port

Bodywork / Breakage




5. Shield / Front

Bodywork / Dent / Dent



6. Rocker Panel / Center Right

Bodywork / Dent / Deformation



7. Door / Back Right

Bodywork / Dent / Deformation




8. Fender / Back Right

Bodywork / Dent / Deformation



9. Shield / Back

Paint / Scratch / Scuff



10. Fender / Back Left

Bodywork / Dent / Dent



11. Door / Back Left

Bodywork / Dent / Dent