

INSPECTION REPORT

End of contract

GENERAL INFO

File	316162
License plate	2ARZ368
Vehicle identification number	KNACC81GFL5041708
Dossier	2021 169 003
Make	Kia e-Niro 150kW More
Mileage	136218
First registration	28/06/2021
client availability date	29/06/2026
inspectionDate	09/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
19	Bumper Front / Lower Cover Not Painted / Replace	N
272	Bumper Front / Trim Right / Replace	N
134	Bumper Rear // Repair & Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
283	Bumper Rear / Trim Right / Replace	N
78	Side View Mirror Left / Direction Indicator / Replace	N
91	Rocker Panel Left // Smart Repair Medium	Y
91	Rocker Panel Left // Smart Repair Medium	N
117	Wing Rear Left / Trim / Replace	N
174	Light / Rear Right / Replace	Y
190	Door Rear Right // Smart Repair Small	Y
201	Rocker Panel Right // Smart Repair Medium	Y
201	Rocker Panel Right // Smart Repair Medium	N
310	Wheel Two Tone Front Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	Y
414	Seat Front Left / Complete Coating / Replace	Y
532	Trunk Compartment / Side Cover Left / Replace	Y

Damage Pictures



Door Rear Right // Smart Repair Small-scratch



Rocker Panel Left // Smart Repair Medium-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Rocker Panel Right // Smart Repair Medium-dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Wing Rear Left / Trim / Replace-scratch



Light / Rear Right / Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch



Side View Mirror Left / Direction Indicator / Replace-cracked



Wheel Two Tone Front Left // Repair-Chemical reaction



Wheel Two Tone Front Right // Repair-Chemical reaction





Seat Front Left / Complete Coating / Replace-worn



Trunk Compartment / Side Cover Left / Replace-scratch



Bumper Front / Trim Right / Replace-scratch



Bumper Front // Smart Repair Large-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch + dent





Bumper Rear // Repair & Painting-scratch + dent



Bumper Rear / Lower Cover Not Painted / Replace-cracked



Bumper Rear / Trim Right / Replace-scratch