



PEUGEOT 3008: FW-782-YB

Vinnumber:	VF3MCYHZULS308869	Versionname:	PEUGEOT 3008 BlueHdi 130 S&S EAT8 Active Busine
First Registrationdate:	2/02/2021	Fiscalpower:	VP [5P] bva 8-130CH-7cv (SUV)
Expertise Mileage:	154577	Power Kw:	96
Bodytype:	SUV	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Grey
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Headlights Xenon/LED/Laser	
Windows electric F		Front parking sensors	
Windows electric R		Rear view camera	
Cruise Control		Seat cover lining	Lining Other
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	Autom climate control		

Tyres

215/65/17/99 V			
Summer tyres:	Fr.L.	Goodyear: 15%	Fr.R.
	Re.L.	Continental: 50%	Re.R.
		Goodyear: 35%	Continental: 50%
Tyre profile depth FL			7.1
Tyre profile depth FR			5.9
Tyre profile depth RL			4.9
Tyre profile depth RR			4.9
Tyre size FL			215/65 R 17 99 V
Tyre size FR			215/65 R 17 99 V
Tyre size RL			215/65 R 17 99 V
Tyre size RR			215/65 R 17 99 V
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			259
Tyre make FR			259
Tyre make RL			256
Tyre make RR			256

Assistance equipment

Remote ignition key, Missing, Repair/replace (lump sum)



Seat cover FR, Dirty, Cleaning



Armrest F M, Scratch(es), Replace



Seat cover FL, Dirty, Cleaning



Seat cover RL, Dirty, Cleaning



Wing FL, Scratch(es), Paint



Door FL, Dent(s) and scratch(es), Repair and paint (complete)




Door RL, Scratch(es), Paint



Wing RL, Scratch(es), Paint



Wing trim RL, Scratch(es), Acceptable



Windscreen, Crack, Replace



Bonnet, Scratch(es), Paint



Bumper moulding F, Scratch(es), Replace



Bumper F, Scratch(es), Polish



Wing trim RR, Unclasp(ed), Dismount/Mount



Wing RR, Scratch(es), Paint



Door RR, Scratch(es), Paint




Door FR, Scratch(es), Paint



Luggage compartment cover, Missing, Replace



Fog light RR, Broken, Replace



Bumper R, Scratch(es), Replace



Bumper corner RR, Scratch(es), Paint

