

MAINTENANCE HISTORY

Generation date: 2024/11/25

Plate Number **G6-07-NR**
 Make **HYUNDAI**
 Model **Ioniq**
 Vehicle Description **EV Comfort 5d**

| DATE | MILEAGE | TYPE | DESCRIPTION |
|------------|----------|--------|---|
| 2024/10/29 | 0 KM | damage | <ul style="list-style-type: none"> Ruit Ruitreductie Z |
| 2023/07/05 | 0 KM | damage | <ul style="list-style-type: none"> Harsrepair ruitschade reparabel |
| 2024/04/26 | 36303 KM | repair | <ul style="list-style-type: none"> Koelvl/antivrie - NVT - Bijvullen/-laden |
| 2024/02/29 | 36303 KM | repair | <ul style="list-style-type: none"> 60.000 Km - NVT - Uitvoeren Hybride/Electro - versleten - Vervangen Int luchtfilter - versleten - Vervangen |
| 2023/10/18 | 34108 KM | repair | <ul style="list-style-type: none"> APK zndr beurt - NVT - Uitvoeren Koelvl/antivrie - NVT - Bijvullen/-laden |
| 2022/12/20 | 26747 KM | repair | <ul style="list-style-type: none"> 45.000 Km - NVT - Uitvoeren Ruitenw.blad V - versleten - Vervangen Telem hardware - Electriche storing - Vervangen |
| 2021/11/08 | 15362 KM | repair | <ul style="list-style-type: none"> 30.000 Km - NVT - Uitvoeren |
| 2020/10/13 | 7502 KM | repair | <ul style="list-style-type: none"> 15.000 Km - NVT - Uitvoeren |