

Expertise

Protocol number: 37059275
Order No. / Reference: 24086897
Inspection date: 18 Nov 2024

Manufacturer: Skoda

Model: Kodiaq 2.0 TDI 4x4 DSG Sportline

VIN: TMBLK7NSXL8512140



Vehicle details

Manufacturer / Type / Model / Equipment

Skoda Kodiaq 2.0 TDI 4x4 DSG Sportline

Vehicle Identification number TMBLK7NSXL8512140

Mileage (Read) 178,780 km

First registration 25 Feb 2020

Number of holders 1

Power / Engine displacement 140 kw / 1,968 ccm

Fuel type / Cylinder Diesel / 4

Gearbox / Number of gears Automatic / 7

Type of drive All-wheel drive

Type of vehicle SUV

Colour / colour code Moon-Weiß Perleffekt

Doors / Seats 5 / 5

Upholstery type Alcantara / Leather

Colour of upholstery Black-Anthracite



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	29,400 km
Last maintenance on / at	10/2024 at 178,123 km		
Key is / should be	3 / 3	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available
		LetterNo	FR665825
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	Sufficient	lifting equipment / pit	yes
Test drive	Short drive around the company premises	Engine function test	Performed
Manufacturer key number/ type code number	8004 / ARX 00092		
Emission standard	EURO6;WLTP;DG;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,400 kg	Empty weight	

Tyres

Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R18 104H	Winter tyres on Light alloy	Goodyear	5mm / 5mm
2)	235/55 R18 104H	Winter tyres on Light alloy	Goodyear	5mm / 5mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/50 R19 103V	Summer tyres on Light alloy	Nokian	6mm / 6mm
2)	235/50 R19 103V	Summer tyres on Light alloy	Nokian	6mm / 6mm
Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 10/2023		

Legend: Tread depth indication for left-hand tires in first place, for right-hand tires in second place on the axle in the direction of travel



Equipment

Standard equipment

- storage compartment on the left wheel house
- Storage compartments (Ticket holder on the windscreen Closed storage compartment on the driver's side 4 roof grab handles, rear with coat hooks Coat hook on the B-pillar High visibility vest compartment in the front doors Glasses compartment on the roof lining Storage compartments in the door panels (front and rear) with bottle holder (1.5l front, 1l rear) Storage net on the passenger side of the center console (except Active) Cup holder in the front center console with "Easy-Open" bottle opening Storage pockets on the front seat backrests)
- traction control (ASR)
- Electrically folding exterior mirrors including interior and exterior mirrors with automatic dimming
- Hill start assist
- brake assist, hydraulic
- cargo elements in the trunk
- Black headliner
- Carbon decorative insert with SPORTLINE logo
- Tachometer
- Easy Start (start-stop button instead of the ignition lock)
- Electronic transverse differential lock (XDS+)
- ESC Electronic Stabilization Control
- Driving light assistant and rain sensor (tunnel light, coming and leaving home function))
- Chassis: Adaptive chassis DCC including off-road assistant
- Front radar assistant including city emergency braking function with person detection
- Cruise control system
- Tinted windows
- glove compartment illuminated
- heated rear window
- ISOFIX preparation on the outer rear seats (including top tether)
- Trunk cover, rollable and removable
- Headrests firmly integrated at the front, height adjustable at the rear
- LED ambient lighting (decorative strips in the door panels with selectable color climate, LED reading lights at the front, LED lighting for the make-up mirrors in the sun visors)
- LED taillights in crystal glass look & LED license plate lighting
- Steering wheel: Sports steering wheel with multifunction buttons including shift paddles (steering wheel with radio controls)
- front center armrest, including storage compartment
- MSR (engine drag torque control)
- fog lights with integrated LED daytime running lights
- network program in the trunk
- pedals in stainless steel design
- Upholstery: Microfibre Alcantara Sport Black
- Storage compartments behind the wheel house in the trunk
- front aero wipers
- Airbag, driver and front passenger (passenger airbag can be switched off)
- airbag, driver's knee airbag
- airbag, head airbags
- airbag, front side airbags
- Allergen filter
- all-wheel drive permanent
- anti-lock braking system (ABS)
- Dashboard in black / black, door trim in black with Alcantara inlay
- Electrically adjustable and heated exterior mirrors with integrated side indicators
- Care Connect: Proactive Services (14-year term) (Remote Access (1-year term))
- Roof rails, black
- Diesel particulate filter
- Third brake light (in the rear spoiler (LED))
- Electronic parking brake including auto-hold function
- Emergency Call (automatic emergency call function in the event of an accident with airbag deployment)
- Driving profile selection including personalizable key (Normal, Eco, Sport, Individual)
- Electric windows front and rear (including anti-pinch protection and child safety lock)
- floor mats front and rear
- Footwell lighting front and rear
- Transmission: 7-speed dual-clutch transmission (DSG)
- Green tec (automatic start/stop including brake energy recovery)
- Rear window wiper Aero including windshield washer system
- Climatronic air conditioning (2 zones) (fully automatic, separately adjustable for driver and front passenger including humidity sensor, odor and allergen filter and climate-controlled glove compartment)
- LED headlights with LED daytime running lights (including adaptive headlights (AFS): lighting system with fully automatic and situation-dependent light control (city, country, motorway and bad weather mode), cornering lights, automatic headlight range control)
- Steering wheel: 3-spoke leather steering wheel (height and length adjustable 3-spoke leather steering wheel - gear lever with leather elements)
- Rear center armrest with cup holders and through-loading option



- Progressive steering
- Radio: Music system Swing 6.5" (incl. SD card slot - mp3 player)
- Radio accessories: Digital radio reception DAB+
- Tire mobility set (tire repair spray including compressor)
- Wheels: 19" alloy wheels Triglav anthracite-polished (7Jx19 tires 235/50 R19 99V ET43)
- Heated windscreen washer nozzles
- Power steering, electromechanical
- Seats: Heated front and outer rear seats
- Seats: Electrically adjustable front seats with memory function
- Seats: Driver and passenger seat height adjustable (including adjustable lumbar supports)
- 12V socket - in the center console and in the trunk
- Bumpers painted in body color (exterior mirrors and door handles painted in body color)
- Sunset (rear window and rear side windows dark tinted)
- Telephone: Comfort hands-free telephone system (without connection to the external antenna) including paddle shifters (steering wheel with multifunction buttons - steering wheel with radio controls)
- Variable fastening concept in the trunk (only for 5-seater)
- Immobiliser

Extra equipment

- Finish: pearl effect
- Package: Business Columbus (Scout, Sportline) (Dyn. Radio-Nav. Columbus with mp3 chapter 9, 2" color display, color Maxi-Dot display, traffic sign recognition, SmartLink+ DVD drive, 2 SD card slots, premium telephone hands-free, SAP voice control, SIM card slot (LTE support), phone box with inductive charging (connection via external antenna), WLAN hotspot (data connection via the SIM in the LTE modem or via the paired mobile phone), fatigue detection, 230 V plug and USB, electric tailgate control, luggage net partition, Infotain.Online (running time 3 years))
- Swivel trailer coupling (with electric release, including trailer stabilization)

- Multifunctional display with Maxi-Dot display (on-board computer) (with the following functions, among others: time, outside temperature, current consumption, average consumption, distance travelled, driving time, average speed, fuel range, maintenance interval display, door and trunk lid warning, display of information from radio, navigation system and telephone (if available))
- Radio accessories: 8 speakers
- Radio accessories: USB port in the center console
- tire pressure monitoring
- Rear seat backrest 60:40 split folding, longitudinally adjustable, adjustable backrest angle
- Headlights washer / wiper system
- Seat belts Kodiaq (Height-adjustable three-point seat belts at the front, with belt tensioners - Three three-point seat belts at the rear - Belt fastening signal at the front and in the second row of seats)
- Skoda Care Connect (Proactive services (term 14 years) Remote Access (term 1 year) SOS emergency call function (Emergency Call including automatic activation in the event of an accident with airbag deployment) Mobility service (connection option for quick help in the event of a breakdown) Information service (connection option to the hotline for all questions about vehicle functions) Free remote vehicle access for 1 year (Remote Access) with access to vehicle data and functions via smartphone)
- Front door sills
- lashing eyes in the trunk
- Central locking with radio remote control

- Digital instrument cluster (Virtual Cockpit) (with the following functions, among others: time, outside temperature, current consumption, average consumption, distance travelled, driving time, average speed, fuel range, maintenance interval indicator, door and trunk lid warning, display of information from radio, navigation system and telephone (if available))
- High beam assistant
- Package: Family (Removable waste bin for the door panel - Sun blinds for the rear side windows - Door edge protection - Electric adjustment of the child safety lock)
- parking sensors front & rear
- running boards



Brief expert findings

Documents submitted	At the time of the inspection, the registration certificate part 2 (letter) was available, but the registration certificate part 1 (certificate) was not available. (Copy)
VIN comparison	The vehicle identification number (VIN) was read and its conformity with the documents submitted was verified during the inspection by the undersigned.
Inspection	The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions that can be reproduced using the photo system included in the report. Lifting equipment and a pit were available to examine the vehicle.
Test drive	A short maneuvering and shunting trip was carried out on the company premises
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Front bumper	Cover bumper - front - Damaged - Replace
3	Rear bumper	Rear bumper - Scratched - Smart repair
4	Side panel - rear right side	Brightware - Damaged - Replace
5	Mudguard - left side	Brightware, grille - Damaged - Replace
6	Door - front left side	Brightware - lower - Damaged - Paint
7	Door - rear left side	Brightware - lower - Damaged - Paint
8	Front bumper	Spoiler - Scratched - Paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Bonnet	Bonnet - Dent / paintcoat damage - No deduction

The vehicle shows signs of wear consistent with its age and use.

order/scope of the order

The order was placed to prepare a sales report on the vehicle described. This includes the following:

- Description of core relevant information about the vehicle
- Documentation of equipment features
(*delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.
(*Functional tests of driver assistance systems are not included in the scope of services!*)
- a photo documentation of the vehicle



Basis for the order

The basis of this product is the guideline for vehicle returns and assessments of Alphabet Fuhrpark GmbH. The expert makes the explicit findings in individual cases objectively within the framework of the specified standards based on his own expertise.

The vehicle inspection takes place in a non-disassembled condition.

Damage or defects that can only be identified during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An increased risk exists due to concealed defects that were caused by fraudulent deception and were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects which, according to the underlying standard, can no longer be attributed to normal use or wear and tear, are listed in the product under value-reducing factors.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% or pro rata depending on the vehicle's age and mileage.

Previous damages

Neither repaired nor non-repaired previous damage to the vehicle could be determined.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument cluster



Figure 9: Instrument panel



Figure 10: Interior 360° view ([Online Link](#))



Figure 11: Cargo area



Figure 12: VIN



Figure 13: Mounted tyres



Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Front bumper: Cover bumper - front - Damaged - Replace



Damage 2: Front bumper: Cover bumper - front - Damaged - Replace



Damage 3: Rear bumper: Rear bumper - Scratched - Smart repair



Damage 3: Rear bumper: Rear bumper - Scratched - Smart repair



Damage 4: Side panel - rear right side: Brightware - Damaged - Replace



Damage 4: Side panel - rear right side: Brightware - Damaged - Replace



Damage 5: Mudguard - left side: Brightware, grille - Damaged - Replace



Damage 5: Mudguard - left side: Brightware, grille - Damaged - Replace



Damage 6: Door - front left side: Brightware - lower - Damaged - Paint



Damage 6: Door - front left side: Brightware - lower - Damaged - Paint



Damage 7: Door - rear left side: Brightware - lower - Damaged - Paint



Damage 7: Door - rear left side: Brightware - lower - Damaged - Paint



Damage 7: Door - rear left side: Brightware - lower - Damaged - Paint



Damage 8: Front bumper: Spoiler - Scratched - Paint



Damage 8: Front bumper: Spoiler - Scratched - Paint



Damage 8: Front bumper: Spoiler - Scratched - Paint