



NISSAN QASHQAI

Qashqai 1.6 dCi 130 Stop/Start Acenta Xtronic A

VIN NO SJNFDAJ11U1455241

Registration Number DW178BJ



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCAuto Encheres	Mechanical Grade	
Inspection Date / Place	2026-04-15 / BCA NANTES	Cosmetic Grade	1


Vehicle Summary


Vehicle Condition	Runner	VAT Type	Exempt Rate
Fuel Type	Diesel	Gearbox Type	Auto clutch
Colour	White	Engine Size (cc)	1598
Engine Size	1.6	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Charging Cables		No of Seats	5
NEDC CO2 Rating (q/km)	122	Seat Covering	
Engine Rating CV	7	Metalic Colour	
Accident Damage	No	Euro Emission	
First Registration / Construction Year	2015-09-28 / 1900-01-01	Arrival Date	2026-04-13

Vehicle History & Documents

Service Book Available	Present	Previous Usage	Normal Use
Manufacturer Warrenty		Odometer Warranty	No
Next Service Mileage	km	Imported	No







Equipment

Central locking	Electrically folding wing mirrors	Rear parking sensors	Stability control
Cruise control	Front parking sensors	Roof rails	Electrically adjustable seats
Radio	Alloys wheels	Tow ball	Front fog lamps
Power assisted steering	Satellite navigation		

Equipment Details


Presence Anti-Theft Lock Nut	Ok	Air Conditioning	Yes
Seat Heating	No		

Wheels & Tyres


Left Rear Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Right Front Tyre Depth	5

Cosmetic Damage

4 identified damages



0 identified damages



Component	Damage	Comments
1 Rim / Front Left	Out of Bodywork / Scratch	
2 Bumper / Back	Paint / Chipping	
3 Door / Front Right	Paint / Chipping	
4 Bumper / Back	Paint / Chipping	



1. Rim / Front Left
Out of Bodywork / Scratch -



2. Bumper / Back
Paint / Chipping -



3. Door / Front Right
Paint / Chipping -



4. Bumper / Back
Paint / Chipping -

Mechanical Condition

Levels			
Oil Condition	!	Level - Oil	✓
Coolant Fluid - Condition	✓	Coolant Fluid level	!
Brakes Fluid	✓		
Engine			
Cross Member	✓	Serpentine Belt	✓
Control Liquid Leak	!		
Equipments Test			
Main & Spare Keys Functioning	✓	Parking Sensors / Cameras Functioning	✓
Convertible, Sunroof, Wagon, Flatbed truck, Tailgate electrics test	NA	Dump / Trail / Tail Gate Lift	NA
Electric Windows	✓	Audio Equipment	✓
Navigation System	✓	AC / Heating System	✓
Central Locking	✓		
Dashboard Lights			
ABS Warning Light	✓	Transmission Warning Light	✓
Diesel Particulate Filter Light	✓	ESP Fault/Traction Control Malfunction Light	✓
4WD Light	NA	Service Light	✓
Dashboard Working	✓	Engine Light	✓
Oil Pressure Warning Light	✓	Airbag Warning Light	✓
Brake Warning Light	✓	Steering Fluid Level	NA
Level - Fuel / Battery	50		
Hybrid/EV			
Charge Port Condition	NA	Charge lead 1 condition /Charge lead 2 condition	NA
Hybrid System Fault	NA		

Test Drive Inspection

Test Drive

Engine functioning	✓	Engine / Aux Belt / Pulley Noise	✓
Steering Noise/Gripping	✓	Vehicle Starts	✓
Engine Power	✓	Smoke Quantity	!
Transmission	✓	Clutch Functioning	NA
Brakes Functioning	✓	Steering	✓

✓ *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

! *Damages or malfunction detected that requires repairs by the buyer*

NA *Not applicable*

☐ *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.