



RENAULT MEGANE ESTATE: FJ-342-KG

Vinnumber:	VF1RFB00863589192	Versionname:	RENAULT MEGANE ESTATE Business Blue dCi 95
First Registrationdate:	7/08/2019	Fiscalpower:	VP [5P] bvm 6-95CH-5cv (break)
Expertise Mileage:	189060	Power Kw:	70
Bodytype:	Break	Interior colour:	Black
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:	Front	Paint type:	Metalic
Fueltype:	Diesel	Dashboard color:	Black
Number of doors:	5	Body colour:	Dark Blue
Engine functioning:	Yes		
Type of rims (mounted):	Steel		
Number head rests:	5		
Category:	Passenger Car		
Vehicle running:	Yes		
Battery functioning:	Yes		
Number of seats:	5		

Options

GPS big screen color	Radio	
Steering wheel multifunctional	Seat cover lining	Lining Other
Number keys remote	2	
Cruise Control	Rear parking sensors	
Windows electric R	Central consol F	
Type of climate control	Front parking sensors	
Steering wheel leather		
GPS storage		
GPS storage	HD	
Number of keys total	2	
Windows electric F		

Tyres

Tyre size RL	205/55 R 16 91 V
Tyre type FL	Summer
Tyre type RL	Summer
Tyre profile depth FR	6.2
Tyre profile depth RR	6.5
Tyre size FR	205/55 R 16 91 V
Tyre make FR	261
Tyre size RR	205/55 R 16 91 V
Tyre make RR	261

205/55/16/91 V

Summer tyres:	Fr.L.	Michelin: 25%	Fr.R.	Michelin: 30%
	Re.L.	Michelin: 20%	Re.R.	Michelin: 25%

Tyre profile depth FL	6.5
Tyre type FR	Summer
Tyre make FL	261
Tyre size FL	205/55 R 16 91 V
Tyre type RR	Summer
Tyre profile depth RL	6.8
Tyre make RL	261

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Floor mat F, Tear, Replace



Seat cover FL, Stain, Cleaning



Interior covering B pillar L, Scratch(es), Repair/replace (lump sum)



Outer sill L, Dent(s), Repair and paint (complete)



Bumper F, Deformed / Strained, Replace and paint



Luggage compartment cover, Missing, Replace



Bumper R, Deformed / Strained, Repair and paint (complete)

