



IDENTIFICATION VEHICLE

Make:	KIA
Model / version:	E-NIRO
Vin:	KNACC81GFL5041264
Plate:	1YJF739
Mileage:	138732
First registration:	09/09/2020
Color:	



ADDITIONAL INFORMATION








Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	

DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Maintenance book:	
Number of keys:	2
Original key:	✓

PICTURES





VIN INFORMATION

EQUIPMENT

Board computer:	?	Central locking:	?
Compressor:	?	Cruise control:	?
Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	?
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	1	Fast charging cables:	1

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm			All-seasons		?
Front right	5 mm			All-seasons		?
Rear left	5 mm			All-seasons		?
Rear right	5 mm			All-seasons		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
2	Grill	Broken
4	Bonnet	Dent(s) and scratch(es)
9	Rear light R	Crack
11	Inner door sill RR	Dent(s) and scratch(es)
12	Door RR	Scratch(es)

Total: 5

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
1	Boot lid covering R	Scratch(es)	✓	✗	✗
3	Bumper F - Polierbaar	Scratch(es)	✓	✗	✗
5	Wing FL	Scratch(es)	✓	✗	✗
6	Door RL - Polierbaar	Scratch(es)	✓	✗	✗
7	Bumper R	Scratch(es)	✓	✗	✗
8	Tailgate / Boot - Polierbaar	Scratch(es)	✓	✗	✗
10	Wing trim RR	Scratch(es)	✓	✗	✗
13	Wing FR	Dent(s)	✓	✗	✗
14	Roof rail R	Scratch(es)	✓	✗	✗

Total: 9

DAMAGES DETAILS

2 - Grill - Broken





4 - Bonnet - Dent(s) and scratch(es)




9 - Rear light R - Crack



11 - Inner door sill RR - Dent(s) and scratch(es)



12 - Door RR - Scratch(es)



1 - Boot lid covering R - Scratch(es) - Renta®




3 - Bumper F - Polierbaar - Scratch(es) - Renta®



5 - Wing FL - Scratch(es) - Renta®



6 - Door RL - Polierbaar - Scratch(es) - Renta®



7 - Bumper R - Scratch(es) - Renta®




8 - Tailgate / Boot - Polierbaar - Scratch(es) - Renta®





10 - Wing trim RR - Scratch(es) - Renta®



13 - Wing FR - Dent(s) - Renta®



14 - Roof rail R - Scratch(es) - Renta®



SIGNATURE

Expert
01/10/2025 15:17
