

APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name: HM Tongeren
Make: RENAULT
Model / version: KANGOO EXPRESS
Vin: VF1WF000X68148934
Plate: 2BFD567
Mileage: 94576
First registration: 29/10/2021
Color:

ADDITIONAL INFORMATION






Category:
Transmission: Front
Interior color:
Metallic paint: ?
Type of lining:
Board computer reset: ✓

DOCUMENTS

Certificate of conformity: ✓
Registration certificate: ✓
Registration certificate 2: ✓
Insurance certificate: ?
Maintenance book:
Number of keys: 2
Original key: ✓

PICTURES





VIN INFORMATION

EQUIPMENT

Board computer:	?	Central locking:	?
Compressor:	✗	Cruise control:	?
Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	✗
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	0	Fast charging cables:	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	3 mm			Winter		?
Front right	3 mm			Winter		?
Rear left	3 mm			Winter		?
Rear right	3 mm			Winter		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Inner door handle FL	Damaged
2	Step L	Grooved
4	Bumper F	Tearred
5	Wing FL	Scratch(es)
6	Door FL	Dent(s) and scratch(es)
7	Bumper R	Deformed / Strained
8	Wing RR	Dent(s) and scratch(es)
9	Door RR	Dent(s) and scratch(es)
10	Door FR	Dent(s) and scratch(es)

Total: 9

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
3	Bonnet - P-controleren vergrendeling motorkap		✓	✗	✗

Total: 1

DAMAGES DETAILS

1 - Inner door handle FL - Damaged



2 - Step L - Grooved



4 - Bumper F - Tearred



5 - Wing FL - Scratch(es)



6 - Door FL - Dent(s) and scratch(es)



7 - Bumper R - Deformed / Strained



8 - Wing RR - Dent(s) and scratch(es)



9 - Door RR - Dent(s) and scratch(es)



10 - Door FR - Dent(s) and scratch(es)



3 - Bonnet - P-controleren vergrendeling motorkap - Renta®



Expert

10/03/2026 14:31

CV