



RENAULT KANGOO ZE HA

Immatriculation	FP-959-SV
VIN	VF1FW000665426231
Kilométrage	104 008 km
Première immatriculation	11/05/2020
Couleur carrosserie	Blanc

DÉTAILS DE L'INSPECTION

Adresse d'inspection	TEA LE MEUX	Date de l'inspection	30/07/2026 09:01:58
Adresse d'inspection	Rue du Bois Barbier 60880 Le Meux		

INFORMATIONS SUR LE VÉHICULE

Marque	RENAULT	Type de carrosserie	Camionnette
Modèle	KANGOO ZE HA	Nbre portes	5
VIN	VF1FW000665426231	Nbre sièges	2
Première immatriculation	11/05/2020	Transmission	Avant
Kilométrage	104 008 km	Couleur intérieur	Noir
Catégorie	Vehicule utilitaire	Couleur carrosserie	Blanc

DOCUMENTS ET CLÉS

Carnet d'entretien	Oui	Manuel d'utilisation	Oui
Nbre clés total	1	Certificat immatriculation (original)	N/A
Nbre clés télécommandes	1	Certificat immatriculation (original)	Non

OPTIONS

Batterie fonctionnante	Oui	Niveau carburant	100
Moteur fonctionnant	Oui	Cric	Oui
Véhicule roulant	Oui	Nature de peinture	Opaque

PNEUS

Pneus montés

Emplacement	Position	Profondeur des sculptures	Fabricant	Dimensions	Type de pneu	Type de jantes	Runflat
Avant	Gauche	4,4 mm	Michelin	195/65 R 15 91 V	Été	Tôle	Non
Avant	Droite	5,2 mm	Michelin	195/65 R 15 91 V	Été	Tôle	Non
Arrière	Gauche	5,1 mm	Michelin	195/65 R 15 91 V	Été	Tôle	Non
Arrière	Droite	4,1 mm	Michelin	195/65 R 15 91 V	Été	Tôle	Non

DAMAGES



Door FL

Damage type

Dent(s) and scratch(es)

Repair mode

Repair and paint (complete)



Side wall RL

Damage type

Dent(s) and scratch(es)

Repair mode

Repair and paint (complete)



Side wall RR

Damage type

Dent(s) and scratch(es)

Repair mode

Repair and paint (complete)



Door FR

Damage type

Dent(s) and scratch(es)

Repair mode

Repair and paint (complete)



Sliding door R

Damage type

Dent(s) and scratch(es)

Repair mode

Repair and paint (complete)





Windscreen

Damage type	Crack
Repair mode	Replace



Boot door panel RR

Damage type	Dent(s) and scratch(es)
Repair mode	Repair and paint (complete)



Boot door panel RL

Damage type	Dent(s) and scratch(es)
Repair mode	Repair and paint (complete)



Bonnet

Damage type	Dent(s)
Repair mode	Repair and paint (complete)



Bumper F

Damage type	Deformed / Strained
Repair mode	Replace



Bumper R

Damage type	Deformed / Strained
Repair mode	Replace



Radio

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)



Wing FR

Damage type	Scratch(es)
Repair mode	Paint



Charging cable (normal)

Damage type	Missing
Repair mode	Replace



Remote ignition key

Damage type	Missing
Repair mode	Repair/replace (lump sum)



Tailgate lock

Damage type	Strained
Repair mode	Replace



Interior

Damage type	Dirty
Repair mode	Cleaning



Wheel arch cover FR

Damage type	Broken
Repair mode	Replace



Brand badge F

Damage type	Broken
Repair mode	Replace



Rubber seal for boot lid

Damage type	Tear
Repair mode	Replace




Tailgate handle

Damage type	Missing
Repair mode	Replace



Door trim FL

Damage type	Deformed / Strained
Repair mode	Replace



Windscreen glue kit

Damage type	Required to install glazing
Repair mode	Repair/replace (lump sum)



Wheel cover FL

Damage type	Broken
Repair mode	Replace





Wheel cover RL

Damage type	Deformed / Strained
Repair mode	Replace



Wheel cover RR

Damage type	Broken
Repair mode	Replace



Wheel cover FR

Damage type	Broken
Repair mode	Replace





Number plate F

Damage type	Broken
Repair mode	Repair/replace (lump sum)



Malfunction indicator

Damage type	Blinking
Repair mode	Check



Outside rear-view mirror housing L

Damage type	Scratch(es)
Repair mode	Acceptable



Outside rear-view mirror housing R

Damage type	Scratch(es)
Repair mode	Acceptable



Bodywork

Damage type	Not original part
Repair mode	Acceptable

COMMERCIAL PHOTOS

