

<b>MACADAM ITALY S.R.L.</b>  Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for <b>Alphabet Italia</b>			Type of insurance <b>Perizia</b>				
				Policyholder			Opposite party			Opposite party company			
				Operation <b>2026</b>	Claim number		Code / Agency			Date accident <b>24/03/2026</b>			
				Expert code		Adjuster code		Policy number		Injured person can recover the VAT			
Date assignment <b>24/03/2026</b>	Date first survey <b>08/04/2026</b>	Place <b>Zibido San Giacomo</b>		C/O <b>RIP</b>	Repairs <b>TO START</b>		Photo	Lien in favor of	Expiry date				
Ownership certificate <b>Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)</b>								Formerly plate					
Lessee / Co-owner								Date of overhaul					
Vehicle (Brand - Model - Version) <b>PEUGEOT 2008 BlueHDi 130 EAT8</b>					Plate <b>GE448ST</b>	Vin Chassis <b>VR3UDYHZSMJ580064</b>		First Registration <b>19/03/2021</b>					
Usage status <b>NON CONOSCIUTO</b>	Km <b>207392</b>	Tyres % <b>30</b>	Color <b>Grigio</b>	Type of enamel <b>METALLIZED/DOUBLE</b>		Consistency of damage <b>YES</b>		Type of Expert's report <b>NOT DEFINITIVE</b>					
Equipment													
Approval code	For commercial vehicles	Carrying Qls <b>0</b>	Tare, Q <b>0</b>	Wheelbase	Seats No. <b>0</b>					Axles <b>0</b>			
Commercial value (C)	Wrecked car value		Value by difference		Ancillary expenses								
Damaged items / restoration operations					SR		LA		VE		ME	D.M. S.C.	Costs of spare parts + (VAT excluded)
1	98259524YS	Trim of rear bumper			S		S		S				
1	16683820XT	Front bumper side grille			L		L		L				
1	982620551T	External rear-view mirror cap			L	L	L	L	L				
1	9831048680	Rear door			L	L	L	L	L				
1	983851711T	Front bumper			L		L		L				
1	Codice Ricambio	Ripristino volante											
1	Codice Ricambio	Lavaggio int.											

New for old value (N)	<b>Remarks</b> Pneum. Nokian 215/60R17 96H inv. post Maxxis 215/60R17 109/107H inv.
-----------------------	--