



Hyundai Ioniq: G233GL

Vinnnummer:	KMHC851JFLU053334	Versionname:	Ioniq EV 100kW / 38kWh Premium DCT
First Registrationdate:	8/11/2019	Fiscalpower:	
Expertise Mileage:	112752	Power Kw:	100
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Electric	Parking lot:	640
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
GPS		Lining leather
Autom climate control		Central consol F
Windows electric F		Luggage cover
Radio multimedia		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors

Degree of wear

205/60/16/92 V				
Winter tyres:	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Bridgestone: 7,5 mm	Re.R.	Bridgestone: 7,6 mm
Tyre profile depth FL				7.0
Tyre profile depth FR				7.0
Tyre profile depth RL				7.5
Tyre profile depth RR				7.6
Tyre size FL				205/60 R 16 92 V
Tyre size FR				205/60 R 16 92 V
Tyre size RL				205/60 R 16 92 V
Tyre size RR				205/60 R 16 92 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

Roof pillar L, Dent(s), Repair and paint (complete)



Bumper F, Broken, Replace and paint



Bumper grille FR, Broken, Replace



LED headlight R, Scratch(es), Repair



Grille, Scratch(es), Replace and paint



Grille frame, Broken, Replace



Shutter / cover F, Missing, Replace



Spoiler FR, Broken, Replace



Bonnet, Dent(s), Repair and paint (complete)



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Rear spoiler, Scratch(es), Repair and paint (complete)



Bumper R, Broken, Replace and paint



Bumper RM, Broken, Replace



Parking sensor R, Missing, Replace

