



Inspection Report

Customer	BCA Sweden	Cosmetic Grade	1
Registration Number	GXE390	Mechanical Grade	B

Vehicle Data

KIA Soul E-SOUL ADVANCE - 2021

Vehicle Identification Number	KNAJ3811FM7022097	Odometer Reading	120624 km
First Registration / Construction Year	2021-05-17 / 2021-03-01	Inspection Date / Place	2025-09-05 / Strängnäs
Fuel Type	Battery Electric Vehicle	Gearbox Type	Automatic
Colour	Red	Number of Keys	1
Service Book Available	Present	Service History	23443, 45928, 84148, 111531
Last Service Km / Date	111531 / 2024-10-01	Arrival Date	2025-09-04

Mounted Tires

Tyre / Wheel Type	Summer
	//R17 / 4 mm
	//R17 / 4 mm
	//R17 / 6 mm
	//R17 / 5 mm

Unmounted Tires

Tyre / Wheel Type	Studded
	//R17 / 5 mm
	//R17 / 5 mm
	//R17 / 8 mm
	//R17 / 8 mm

Equipment

• Heated steering wheel	• Bluetooth
• Cruise control	• Digital Radio
• LED Headlamps	• Rain sensitive windscreen wipers
• Rear parking sensors	• Reversing Camera
• Satellite navigation	

Comments Test Drive

Comment

Checklist

Breaks Noise	Front Noise
Chipped	Stickers
Testdriven	Rear Noise

Damage


Component	Damage
1 Panel Filling / Front Right	Interior / Dented
2 Panel Filling / Back Right	Interior / Scraped
3 Trunk Upholstery / Back	Interior / Dirty
4 Seat / Back Left	Interior / Stained
5 Panel Filling / Back Left	Interior / Dented
6 Panel Filling / Front Left	Interior / Dented
7 Ignition Key	Interior / Missing
8 Rim / Front Left	Out of Bodywork / Scratch
9 Windshield / Front	Glass Break / Impact
10 Rim / Front Left	Out of Bodywork / Scratch
11 Fender / Front Left	Paint / Scratch / Line
12 Tvättrepor på flera paneler/ from wash on different panels	Paint / Scratch / Scuff
13 Rim / Front Right	Out of Bodywork / Scratch
14 Shield / Front	Bodywork / Dent / Deformation


Photo Documentation
















1. Panel Filling / Front Right

Interior / Dented



2. Panel Filling / Back Right

Interior / Scraped




3. Trunk Upholstery / Back

Interior / Dirty



4. Seat / Back Left

Interior / Stained



5. Panel Filling / Back Left

Interior / Dented



6. Panel Filling / Front Left

Interior / Dented



7. Ignition Key

Interior / Missing



8. Rim / Front Left

Out of Bodywork / Scratch

Pris för en fälg/price for one rim



9. Windshield / Front

Glass Break / Impact



10. Rim / Front Left

Out of Bodywork / Scratch



11. Fender / Front Left

Paint / Scratch / Line



12. Tvättrepor på flera paneler/ from wash on different panels

Paint / Scratch / Scuff

Tvättrepor på flera paneler/ from wash on different panels



13. Rim / Front Right

Out of Bodywork / Scratch



14. Shield / Front

Bodywork / Dent / Deformation