



Inspection Report

Customer	BCA Sweden	Cosmetic Grade	4
Registration Number	KBE41D	Mechanical Grade	A

Vehicle Data

KIA Niro e-Niro Advance - 2022

Vehicle Identification Number	KNACC81GFN5150609	Odometer Reading	174149 km
First Registration / Construction Year	2022-02-16 / 2022-01-01	Inspection Date / Place	2025-05-09 / Strängnäs
Fuel Type	Battery Electric Vehicle	Gearbox Type	Automatic
Colour	Black	Number of Keys	2
Service Book Available	Present	Service History	18379,30444
Last Service Km / Date	30444 / 2024-11-14	Arrival Date	2025-05-08

Mounted Tires

Tyre / Wheel Type	Summer
	//R17 / 3 mm
	//R17 / 3 mm
	//R17 / 6 mm
	//R17 / 6 mm

Unmounted Tires

Tyre / Wheel Type	Studded
	//R17 / 2 mm
	//R17 / 2 mm
	//R17

Equipment

• Heated steering wheel	• Bluetooth
• Cruise control	• Digital Radio
• Rain sensitive windscreen wipers	• Rear parking sensors
• Reversing Camera	• Satellite navigation
• Alcohol Lock	• Metallic colour

Comments Test Drive

Comment	P-sensor ur funktion/ parking sensor malfunction
---------	--

Checklist

Stickers	Testdriven
Chipped	

Damage


Component	Damage
1 Roof Upholstery	Interior / Dirty
2 Startknapp/start button	Interior / Missing
3 Cabin	Interior / Worn - out
4 Seat / Front Left	Interior / Holed
5 Tailgate Upholstery / Back	Interior / Broken
6 Door Step / Back Right	Interior / Worn - out
7 Center Console	Interior / Holed
8 Panel Filling / Front Right	Interior / Scratched
9 Windshield / Front	Paint / Chipping
10 Märken efter dekal, repor, mindre skador / marks after stickers, scratches, small damages	Paint / Chemical Damage
11 Shield / Front	Paint / Scratch / Scuff
12 Fender / Front Right	Bodywork / Dent / Dent
13 Wing Expander / Front Right	Paint / Scratch / Scuff
14 Hood	Paint / Chemical Damage
15 Rim / Front Right	Out of Bodywork / Scratch
16 Rim / Back Right	Out of Bodywork / Scratch
17 Door / Back Left	Paint / Scratch / Scuff
18 Door / Front Left	Paint / Scratch / Scuff
19 Fender / Front Left	Paint / Scratch / Scuff
20 Tire / Front Right	Tire
21 Tire / Front Left	Tire
22 Roof	Bodywork / Dent / Dent
23 Missed Service	

Photo Documentation
















1. Roof Upholstery


Interior / Dirty



2. Startknapp/start button

Interior / Missing

Startknapp/start button



3. Cabin

Interior / Worn - out



4. Seat / Front Left
Interior / Holed



5. Tailgate Upholstery / Back
Interior / Broken



6. Door Step / Back Right
Interior / Worn - out



7. Center Console

Interior / Holed



8. Panel Filling / Front Right

Interior / Scratched



9. Windshield / Front

Paint / Chipping



10. Märken efter dekal, repor, mindre skador / marks after stickers, scratches, small damages


Paint / Chemical Damage

Märken efter dekal, repor, mindre skador / marks after stickers, scratches, small damages



11. Shield / Front

Paint / Scratch / Scuff



12. Fender / Front Right

Bodywork / Dent / Dent



13. Wing Expander / Front Right

Paint / Scratch / Scuff



14. Hood

Paint / Chemical Damage



15. Rim / Front Right

Out of Bodywork / Scratch



16. Rim / Back Right

Out of Bodywork / Scratch



17. Door / Back Left

Paint / Scratch / Scuff



18. Door / Front Left

Paint / Scratch / Scuff



19. Fender / Front Left
Paint / Scratch / Scuff



20. Tire / Front Right
Tire



21. Tire / Front Left
Tire



22. Roof

Bodywork / Dent / Dent