



HYUNDAI TUCSON: GH-693-XG

Vinnumber:	TMAJD811BNJ119801	Versionname:	HYUNDAI TUCSON 1.6 HYBRID 230 CREATIVE VP [5P] bva 6-230CH-10cv (SUV)
First Registrationdate:	4/08/2022	Fiscalpower:	
Expertise Mileage:	147797	Power Kw:	169
Bodytype:	SUV	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Interior colour:	Black
Fueltype:	Hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Central consol F	
GPS big screen color		Luggage cover	
GPS storage		Headlights Xenon/LED/Laser	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Rear view camera	
Cruise Control		Seat cover lining	Lining Other
Steering wheel multifunctional			
Steering wheel leather			
Seats F heated			
Type of climate control	Autom climate control		

Tyres

	215/65/17/99 V			
Summer tyres:	Fr.L.	Continental: 25%	Fr.R.	Continental: 30%
	Re.L.	Michelin: 45%	Re.R.	Michelin: 45%
Tyre profile depth FL				6.4
Tyre profile depth FR				6.3
Tyre profile depth RL				5.4
Tyre profile depth RR				5.1
Tyre size FL				215/65 R 17 99 V
Tyre size FR				215/65 R 17 99 V
Tyre size RL				215/65 R 17 99 V
Tyre size RR				215/65 R 17 99 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				256
Tyre make FR				256
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Seat cover FL, Stain, Cleaning



Seat cover R, Stain, Cleaning



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)



Wing trim FL, Unclassped, Dismount/Mount



Door FL, Scratch(es), Paint




Internal boot lining L, Scratch(es), Repair/replace (lump sum)



Internal boot lining R, Scratch(es), Replace



Boot lid covering R, Scratch(es), Repair/replace (lump sum)



Tailgate / Boot, Dent(s), Repair and paint (complete)



Bodywork, Not original part, Sticker removal small

